



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor


Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

September 6, 1995

TO: Minerals File

FROM: Lynn Kunzler, Reclamation Specialist 

RE: Site Inspection, Utah Building Stone, Inc., Green Beetle Quarry, S/003/017, Box Elder County, Utah

Date of Inspection: August 31, 1995
Time of Inspection: 7:30 a.m.
Conditions: Bright and sunny
Participants: Tom Munson, and Lynn Kunzler, DOGM

Purpose of Inspection: To document site conditions.

This site is accessed via the Rosebud Road. No one was present on site.

On the west side of the quarry a couple barrels were observed. Labels identified the product as MagicKote from Simons Corp, DesPlains, Illinois; it is a chemical neutral form coating that doesn't stain or discolor concrete. The label includes a caution: combustible, for industrial use only. The product is a diesel fuel solution of some sort. It has a NFPA hazard code of 1-2-1, and includes a 24 hour chemical emergency number to call, 1-800-424-9300. The label also reads, "Danger - after container has been emptied, it contains explosive and harmful vapors and residue. Keep away from heat, sparks, flames; do not cut, puncture, or weld near the container; do not re-use container for any purpose until chemically cleaned." There were a couple more barrels on the east side of the quarry. These barrels were apparently discarded where emptied, (not in a containment or storage area).

There is a small camp(?) area about 60 feet west of the quarry. There are some used oil containers and other debris that needs to be cleaned up. On the north end of the camp area there is an oil drain pan that has a couple of inches of what appears to be waste oil(?).

The disturbed area was measured using the hip chain. It is kind of tear-drop shaped; wider at the north end, tapers at the south end. Approximately 700 feet long, and approximately 250 feet wide through the center of it. This gives approximately 4 acres of disturbance.

Other than the cleanup of the litter, and the need to properly store/dispose of the barrels, this site is OK.

